



Notes

- 1) Each 240V load must have one leg pass through the CT with one complete wrap as shown
- 2) All loads passing through the CT must be on the same phase, and pass through in the same direction
- 3) 120V loads, if authorized by JREC, pass through CT only once

CT Wiring